

Photobook

First Look Tour: Button Rock Preserve





Culvert Below Longmont Reservoir Pre Flood (2013)



Culvert below Longmont Reservoir Post Flood



Culvert below Longmont Reservoir After Repair



Longmont Reservoir – Pre-Flood



Longmont Reservoir Post Flood



Longmont Reservoir – after Repair



Longmont Dam Road



Longmont Dam Road



Ralph Price Reservoir Spillway Confluence at North Saint Vrain Creek during Flood



Ralph Price Reservoir Spillway Confluence at North Saint Vrain Creek Post Flood



Ralph Price Reservoir Spillway Confluence at North Saint Vrain Creek Post Flood



Ralph Price Reservoir Spillway Confluence at North Saint Vrain Creek after Repair



Ralph Price Reservoir Spillway – Pre-Flood



Ralph Price Reservoir Spillway – During Flood



Ralph Price Reservoir Spillway – Post Flood



Ralph Price Reservoir Spillway – after Repair



Ralph Price Reservoir Spillway – Post Flood



Ralph Price Reservoir Spillway – during Cleanup



Ralph Price Reservoir Spillway –during Cleanup



Woody Debris in Ralph Price Reservoir (During Flood)

Woody Debris Removal at Ralph Price Reservoir
Phase 1 – Removal of Woody Debris from Spillway and Dam



Woody Debris Removal at Ralph Price Reservoir
Phase 2 – Removal of Woody Debris Beach at Inlet



Woody Debris Removal at Ralph Price Reservoir
Phase 3 – Removal of Woody Debris Beached along Shoreline of Ralph Price Reservoir



Woody Debris Removal at Ralph Price Reservoir
Phase 3 – Removal of Woody Debris Beached along Shoreline of Ralph Price Reservoir



Woody Debris Removal at Ralph Price Reservoir
Phase 3 – Removal of Woody Debris Beached along Shoreline of Ralph Price Reservoir



Woody Debris Removal at Ralph Price Reservoir
Phase 4 – Removal of Floating Woody Debris at Inlet



Granular Debris in Inlet Area to Ralph Price Reservoir - Pre-Flood



Granular Debris in Inlet Area to Ralph Price Reservoir - Post Flood



Granular Debris in Inlet Area to Ralph Price Reservoir – After 2014 Runoff

